

Compte rendu à relire

Intervention

DEMO-EVC-001

Équipement

Borne fictive A · Référence à confirmer

Motif

Session de charge interrompue, selon le scénario fictif.

Constat

Le technicien décrit un message d'erreur. Code non communiqué.

Actions rapportées

Inspection visuelle rapportée. Aucune mesure électrique fournie.

Résultat

Remise en service non confirmée. Ne pas conclure au bon fonctionnement.

Pièces et photos

Aucune pièce déclarée. Photo à ajouter si exigée.

Informations manquantes

Code défaut, identifiant équipement, résultat des essais.

Prochaine étape

Compléter les informations puis soumettre au relecteur désigné.

Statut

Brouillon incomplet · Non approuvé

Exemple éditorial de structure, pas une capture du logiciel ni un résultat de pilote.

Service report for review

Job

DEMO-EVC-001

Equipment

Synthetic charger A · Identifier to confirm

Reason

Charging session interrupted in the synthetic scenario.

Observation

Technician describes an error message. No fault code supplied.

Reported actions

Visual inspection reported. No electrical measurements supplied.

Outcome

Return to service is unconfirmed. Do not infer correct operation.

Parts and photos

No parts reported. Add photo if required.

Missing information

Fault code, equipment identifier, test outcome.

Next action

Complete missing information and submit to the designated reviewer.

Status

Incomplete draft · Not approved

Editorial structure example, not a product screenshot or pilot result.